

Northbrook, Illinois • (847) 272-8800
Melville, New York • (516) 271-6200
Santa Clara, California • (408) 985-24
Research Triangle Park,
North Carolina • (919) 549-1400
Camas, Washington • (360) 817-5500



ABB CONTROL INC
MR J BYRNE
1206 HATTON RD
WICHITA FALLS TX 76302



Your most recent listing is shown below. Please review this information and report any inaccuracies to the UL Engineering staff member who handled your UL project.

NKCR October 31, 1997
Auxiliary Devices

ABB CONTROL INC E48139 (R)
1206 HATTON RD, WICHITA FALLS TX 76302 (A card)

Auxiliary contactor, open type, Type K followed by 40, 31, 22 or 13, may be followed by EAU or E. Type K followed by 44, 53, 62, 71 or 80. Type K followed by 55, 73 or 82. Type KC followed by 22, 31 or 40. Type KC followed by 55 or 82. Type KC followed by 44, 53, 62, 71 or 80.

Auxiliary switch, Cat. No. CA6 or CAF6 followed by 11E, 11K or 11M; Cat. No. CA5-10, -01; CA5-40, -31, -13, -22; CAL5-11; Cat. No. CA7- followed by 10 or 01, may be followed by AU; Cat. No. CA7-followed by 40, 31, 22 or 04; Cat. No. CAL7-11.

Open type, auxiliary device, Cat. No. K6 or KC6 followed by 22Z, 31Z or 40E, followed by 14 or 24; N22, N31, N40; Mechanical interlock for A30-A110 Series, VE5-2; for A9-A40, VE5-1, VM5-1.

Open, time-delay contact, Cat. No. TP followed by 40 or 180, followed by D or I.

Replaces E48139A dated September 25, 1997.
334235001 Underwriters Laboratories Inc.®

(Cont. on B card)
F11/0166903
77

For information on placing an order for UL Listing Cards in a 3 x 5 inch card format, please refer to the enclosed ordering information.

UNDERWRITERS LABORATORIES INC.

A not-for-profit organization
dedicated to public safety and
committed to quality service