




DIAGRAM OF CONNECTION
ANSCHLUSS-SCHEMA
SCHEMA DE BRANCHEMENT




Direction of rotation with phase sequence shown in picture
Drehrichtung nach Schaltbild
Direction de rotation avec branchement ci-dessus

CONNECTION OF TERMINALS
ANSCHLUSS DES MOTORS
BRANCHEMENT DES BORNES



Higher speed
Hohe Drehzahl
Grande vitesse



Lower speed
Niedrige Drehzahl
Petite vitesse

Motor No
Maschine Nr
No du moteur

ABB Motors

3GZF321100-3 A


Connection Diagram

Document No:

3GZF321100-3 A

Description:

3-PHASE SQUIRREL-CAGE TWO-SPEED MOTOR



Unit: ABB Motors Oy / MSO

Issued by: M Prusi

Replaces:

Date: 09.03.2001

Approved by: Hannu Piipponen

Replaced by:

ABB Motors

Customer Reference:

ABB